

DRIVER ALERT

FRESNO AREA EXPRESS

49/2003

DATE: October 10, 2003
TO: All Bus Operators
FROM: RICHARD J. DIAZ, Supervisor II *RJD*
SUBJECT: **Radio System - 2003 ORION Buses**

Recently, communications has discovered that some Bus Operators have been replacing the radio handset in the reverse (upside down) position when replacing the handset into the cradle position.

Bus Operators driving this model bus are requested to place the handset into the receptacle in the "upright" position. The new radio system is utilizing an electronic connection that is required in order for the system to operate properly.

Your cooperation is appreciated, if you have any questions regarding this procedure, please contact Control 12 or a supervisor for additional information.

RJD:mr
BRUCE A. RUDD
DEAN S. HUSS
ADMIN.-AA-RD-NS-AD
DISPATCH
SUPERVISORS - OPS Reading File
ATU/READING